

Anexo 5. Certificado Calidad por metro 2 Semestre - 2022

**Programa de seguimiento Flora y  
Vegetación de la quebrada de Camar  
Región de Antofagasta**

Anexo 5. Certificado de calidad de porometro – 2° semestre 2022  
GEOB.SQMSL740.INFO22.ANX005. Programa de seguimiento Flora y Vegetación de la quebrada de Camar

Rev.	Id	Ejecutor	Revisor	Aprueba	Descripción
B	Nombre	IJ	IZ		Anexo 8. Certificado de calibración porometro
	Fecha	09.02.2023	20.02.2023		Rev. (B)
0	Nombre				Anexo 8. Certificado de calibración porometro
	Fecha				Rev. (B)

## Contenido

Figura-1 : Certificado de Calidad porometro.

Figura 1 . Certificado Calidad de Porometro.



**METER**  
METER Group, Inc. USA  
Certificate of Quality Assurance

<b>Model</b>	Leaf Porometer, SC-1	<b>Date</b>	July 16, 2021
<b>Order Type</b>	Controller Serial Number: LP4527	<b>Technician</b>	KH
<b>Sensor Serial Number</b>		<b>Calibration Value</b>	
LPS3821		2204200	

This document is to certify that the instrument indicated above has been tested and approved by the Quality Assurance department at METER Group, Inc. USA , and has shown to function properly and to be free of event flaws or defects.

Manufactured in USA

METER Group, Inc. USA  
2365 NE Hopkins Court, Pullman, WA 99163  
T 509.332.2756 F 509.332.5158  
E info@metergroup.com W metergroup.com